


cuier SENZA 1 \_ GS 470-22

1



x1

2



x1

3



M6x12

x2


4



Ø 4.8x13

x2

5



Ø 5x40

x2

6



Ø 20x Ø 7

x2

7



Ø 8x40

x2

8



Ø 8x40

x4

9



x1